

```

/*****
*****
* Hardware version: CoreV4D2, BASE-BOARDV61, IO-BOARDV6.2;
* Update content: Cancel G04 command, cancel G24 command,
Increase G00 command, immediate value of absolute value, variable; incremental immediate
value, variable
Add 2 formats (angle and radians) Trigonometric operation instructions SIN, COS, TAN, ASIN,
ASOS, ATAN
*****
*****/

```

## 1. Serial port instruction

### 1.1 serial port mode

Serial port parameters: baud rate 115200; data bit 8; stop bit 1.

Instruction format:

The control commands are hexadecimal 0X10 (idle mode), 0X11 (file mode), 0X12 (zero return mode), 0X13 (run mode), 0X14 (debug mode), 0X15 (reset mode); 0X05 is the interrogation mode;

The running instructions all start with 'GXX' and end with a carriage return;

The teaching instruction ends with a carriage return and a new line;

In the system version of 180521 and above, when \_flagSoftRst=1 is set in the parameter file, the serial port 1 can send 0X18 to output the output port o14 in any case. According to this function, the e14 relay control NRST restart (emergency stop).

0X05: == query mode ==

The control card is in any working mode (except file mode), and the serial port sends 0X05 to ask the current working mode of the control card. The return value is 0X10, 0X12, 0X13, 0X14, 0X15.

0X10: == enter idle mode ==

When the control card is in idle mode (0X10): it is in idle mode.

In file mode, 0X10 is valid after the file operation instruction is run.

In the zero return mode, the robot stops moving (send 0X30) and sends 0X10 to take effect.

In the running mode, the robot stops moving (send 0X30) and sends 0X10 to take effect.

In reset mode, the reset completes the brake and exits to idle mode. It is in idle mode when it is turned on.

0X11: == enter file mode ==

Download the running file and select "Send File" after sending 0X11. Among them, the first act in the file

"wr=ST" is the run file;

"WR=INI" is a parameter file;

"WR=oq" is a zero return file;

"WR=T\_0" is the default run file, equivalent to "wr=ST";

"WR=T\_1" is the run 1 file;

"WR=T\_2" is the run 2 file;

...

"WR=T\_120" is the run 120 file;

The second behavior file name; the third behavior file length, the length is the file size except the first three lines.

After reading the running file and sending 0X11, send "WR=R,###" ("###" is the length of the read content) to receive the running file.

After reading the parameter file, send "WR=P,###" ("###" is the length of the read content) after sending 0X11 to receive the parameter file.

After reading the parameter file, after sending 0X11, send "WR=Q,###" ("###" is the length of the read content) to receive the zero return file.

The read parameter file can receive the run 0 file after sending 0X11 and sending "WR=H\_0,###" ("###" is the read content length).

After reading the parameter file, send "WR=H\_1,###" ("###" is the length of the read content) after sending 0X11 to receive the run 1 file.

...

After reading the parameter file, after sending 0X11, send "WR=H\_120,###" ("###" is the read content length) to receive the run 120 file.

0X12: == Motor zero return mode ==

After entering the zero return mode, the system automatically runs the file content and the instructions sent by the serial port in real time. Pause is 0X30, continue to 0X12, exit is 0X10

Instructions can be obtained from the run file and can also be obtained from the serial port.

Automatically exit idle mode after running the contents of the file

0X13: == enter running mode ==

After entering the running mode, the system automatically runs the file content and the instructions sent by the serial port in real time. The pause is 0X30, the continuation is 0X13, and the exit is 0X10.

Instructions can be obtained from the run file and can also be obtained from the serial port.

After running the contents of the file, it automatically runs from the beginning.

0X14: == enter debug mode ==

Send 0X05 as the inquiry mode.

Send 0X10 as the exit mode.

Send "0" to stop and send the angle of each axis of the machine.

Send "SVON=1" for servo enable.

Send "SVON=0" to disable the servo.

Send "SVBM=1" to the servo without holding the brake.

Send "SVBM=0" as the servo brake.

Send "CLR=ST\_PUL" to clear the position of the control card.

Send "CLR=SV\_ALM" to clear the drive alarm.

Send "J#+ " to the #axis angle plus motion (#=1, 2, 3, 4, 5, 6).

Send "J#-" to the ##axis angle minus motion.  
 Send "J#0" to stop at ##axis angle.  
 Send "J#<" to repeat the motion for the #axis angle (@0° ~ -90° ).  
 Send "J#>" to repeat the motion for the #axis angle (@ 0° ~ 90° ).  
 Send "P VE=####" to change the running speed to #### pulses/sec.  
 Send "P AC=####" to change the acceleration to #### pulses/square sec.  
 Send "P DE=####" to change the deceleration to #### pulses/square sec.  
 Send "G00 J#=####,...." to get the robot joints to the appropriate angle.  
 Send "G07 \*\*=####" to specify parameters for changing the robot.

TX+: Cartesian coordinates X+;

TX-: Cartesian coordinates X-;

TY+: Cartesian coordinates Y+;

TY-: Cartesian coordinates Y-;

TZ+: Cartesian coordinates Z+;

TZ-: Cartesian coordinates Z-;

TA+: Cartesian coordinates A+;

TA-: Cartesian coordinates A-;

TB+: Cartesian coordinates B+;

TB-: Cartesian coordinates B-;

TC+: Cartesian coordinates C+;

TC-: Cartesian coordinates C-;

P CYCP1=800000: The J1 axis is subdivided into 800,000 pulses per week

....

P J1=24000 Assignment to J1

....

P=VE Query VE value There are VE, AC, DE, CYCP1,....,J1,....,H0,D1,H2...

0X15: == enter reset mode ==

Return the machine to zero.

## 2. Button control instructions

When starting up, press the "Start" button to run the robot to run mode.

In the operating mode, at runtime, press the "Stop" button to pause the machine.

In the operating mode, when stopped, press the "Start" button and the machine continues to run.

In the operation mode, when stopping, press the "Stop" button and then press the "Start" button, the machine resets and exits the idle mode.

Instruction description:

//=====

G0n=GGN such as G06 O=P1.1 is equivalent to GG6 O=P1.1

Point-to-point command G00, G20

G00 J1=0 J2=0 J3=-90 J4=0 J5=-90 J6=0 //with acceleration and deceleration absolute joint

position command

G00 J1=VXX J2=0 J3=VXX J4=VXX J5=-90 J6=0 //With acceleration and deceleration Absolute joint position command

G00 ... J2'4 J3'VXX ... //with acceleration and deceleration relative joint position command

G00 ... J2'4 J3'VXX J4=VXX J5=-90... //J2 is

G20 X=300 Y=100 Z=500 A=0 B=180 C=0 D=0 //with acceleration and deceleration

G20 X=300 Y=VXX Z=VXX A=VXX B=180 C=VXX D=0 //with acceleration and deceleration

G30 EQ01 J1=UXXXX, J2=UXXXX, J3=UXXXX Read memory contents G30 EQ01 J1=U30100 J2=U30120 J3=U30140 J4=U30160

G30 EQ02 U3060=XX.XX Write memory contents G30 EQ02 U30500=10

G30 EQ03 ASK=UXXXX Query memory contents

G30 EQ04 Vxx=UXXXXXX

G30 EQ05 UXXXXXX=Vxx

G40 X=300 Y=100 Z=500 A=0 B=180 C=0 D=0 //No acceleration/deceleration

Linear command G01 G21

G01 J1=0 J2=0 J3=-90 J4=0 J5=-90 J6=0

G21 X=300 Y=100 Z=500 A=0 B=180 C=0 D=0

G21 X=VXX Y=VXX Z=500 A=0 B=VXX C=0 D=0

G41 X=300 Y=100 Z=500 A=0 B=180 C=0 D=0 //with acceleration and deceleration

G41 X=300 Y=VXX Z=VXX A=0 B=180 C=0 D=0 //with acceleration and deceleration

Arc command G02 G03 G04 G22 G23 G06 DEGREE=ARC (or degree)

When DEGREE=ARC is going to be a three-point arc

Current point: G21 X=200 Y=0 Z=200 A=-180 B=150 C=0 D=0

Second point: G22 X=300 Y=100 Z=200 A=-180 B=150 C=90 D=0

Third point: G23 X=400 Y=0 Z=200 A=-180 B=150 C=300 D=0

Arc running: G06 DEGREE=300

//=====

G06 directive

G06 T=500 delay 500 milliseconds

G06 t=VXX Delay VXX content milliseconds (for example: G08 MOV V400=#2000 G06 t=V400 is a delay of 2000 milliseconds)

G06 I=P1.1 Wait for P1 to be high

G06 I=P2.0 Wait for P2 to be low

G06 O=P1.1 makes output port P1 high (different port from input port)

G06 O=P2.0 makes the output port P2 low

G06 SCAN=I Read input port value, stored in V144-V150 unit

G06 SCAN=O Read output port value, stored in V160-V166 unit

G06 SCAN=RTC Read system clock value and store it in V176-V179 unit

G06 DEGREE=ARC robot takes a three-point arc

G06 DEGREE=35.2 The robot walks 35.2 degrees

G06 REPOS=J# J# Axis looks for HOME# sensor from angle increase direction (return to low level)  
 G06 REPOS=-J# J# axis finds HOME# sensor from angle reduction direction (return to low level)  
 G06 REPOS=J1 J1 axis finds HOME0 sensor from angle increase direction (return to low level)  
 G06 REPOS=-J1 J1 axis finds HOME0 sensor from angle reduction direction (return to low level)  
 G06 REPOS=JH# J# Axis finds HOME# sensor from angle increase direction (return to high level)  
 G06 REPOS=-JH# J# axis finds HOME# sensor from angle reduction direction (return to high level)  
 G06 REPOS=JH1 J1 axis finds HOME0 sensor from angle increase direction (return to high level)  
 G06 REPOS=-JH1 J1 axis finds HOME0 sensor from angle decrease direction (return to high level)  
 //=====

**G07 command**  
 G07 VE=250000 speed is 250,000 pulses per second  
 G07 AC=250000 Acceleration is 250,000 pulses per second squared  
 G07 DE=250000 Deceleration is 250,000 pulses per second squared  
 G07 VPP=250000 Maximum speed 250,000 pulses per second  
 G07 VP=20 Speed VE is 20% of the highest speed,  $VE=VPP*VP*0.01$   
 G07 vp=VXX Speed VE is the content of the highest speed VXX,  $VE=VPP*VXX$  unit value  
 \*0.01  
 G07 \_h0=xx height change  
 G07 RCM=1 print run command, 0 does not print run command  
 G07 GCM=1 is output at right angle coordinates when teaching, 0 is joint coordinate output  
 G07 MARKPOS\_HERE X1=0 Y1=0 X2=100 Y2=100 Template MARK point  
 G07 MARKPOS X1=10 Y1=10 X2=110 Y2=110 Match MARK point  
 G07 UNIT=1.0 Interpolation accuracy (in mm)  
 G07 P J#=XXXX calibration J# axis  
 // =====

**G08 instruction**  
 G08 XXXX: Tags No comments are allowed after the tags. The length of the tags must be less than 15 bytes.  
 G08 ACALL XXXX Call XXXX label to G08 END  
 G08 END call ended  
 G08 AJMP XXXX Jump to XXXX operation  
 G08 FLTAB = # file jumps to T\_ # file to run;

G08 IF VXX> = VXX ACALL XXXX Integer comparison Immediate number is # comparison> =, <=, =, !=, >, <; (G08 IF VXX> = VXX AJMP XXXX)  
 G08 IF\_ELSE VXX> = VXX? ACALL XXXX: ACALL XXXX Before the true value runs the colon, after the false value runs the colon ACALL is the call and AJMP is the jump (G08 IF\_ELSE VXX> = VXX? AMMP XXXX: AJMP XXXX)  
 G08 IFF floating point comparison  
 G08 IF\_ELSEF floating-point comparison

G08 MOV VXX = # XX Integer transmission (immediate G08 MOV V10 = # 12) (unit G08 MOV V10 = V12)  
 G08 MOVF VXX = # XX integer transmission (immediate G08 MOVF V10 = # 12.5) (unit G08 MOVF

V10 = V12)

G08 PRINT VXX prints the value of VXX as an integer

G08 PRINTF VXX prints the value of VXX, floating point

G08 INT VXX converts floating point to integer \*\*\*\*\*

G08 FLOAT VXX converts integer to floating point

G08 ADD VXX = VXX + VXX Integer The immediate value is #

G08 SUBB VXX = VXX-VXX Integer The immediate value is #

G08 MUL VXX = VXX \* VXX Integer The immediate value is #

G08 DIV VXX = VXX / VXX Integer The immediate value is #

G08 SQRT VXX = VXX Integer The immediate value is #

G08 ADDF VXX = VXX + VXX Floating point The immediate value is #

G08 SUBBF VXX = VXX-VXX floating point immediate number is #

G08 MULF VXX = VXX \* VXX Floating point The immediate number is #

G08 DIVF VXX = VXX / VXX Floating point The immediate value is #

G08 SQRTF VXX = VXX Floating point The immediate value is #

G08 STO program automatically pauses \*\*\*\*\* 170817 \*\*\*\*\*

G08 EXIT exits and enters idle mode \*\*\*\*\* 170817 \*\*\*\*\*

// =====

G09 instruction

G09 COPYRIGHT Inquiry System YN

G09 COM2 = XXXX COM2 port sends XXXX characters

For example: G09 COM2 = G00 J1 = 10 J2 = 10 J3 = -90 J4 = 0 J5 = 0 J6 = 0

This controller sends instructions to another controller COM1,

G09 COM2 10H Serial port 2 sends 0X10

G09 COM2 12H Serial port 2 sends 0X12

G09 COM2 13H Serial port 2 issues 0X13

G09 COM2 14H Serial port 2 sends 0X14

G09 COM2 15H Serial port 2 sends 0X15

G09 COM2 18H Serial port 2 sends 0X18

G09 ENC .... It is a special instruction to connect with the absolute value servo motor, refer to the zero return file example;

// =====

VXX: Unit

#XX: Immediate

User arithmetic unit V0-V127, V400-V511

The system has used the computing unit to read the input port value and store it in the

V144-V150 unit.

Read the output port value and store it in V160-V166 unit

Read the system clock value and store it in V176-V179

Sending '0' as stop in running mode or when running G code, it is this instruction when continuing; '.' is also stop, it is the next instruction when continuing;

STA real-time key value is stored in V180 unit, key value is stored in V183 unit, V183 is cleared by software

STO real-time key value is stored in V181 unit, key value is stored in V184 unit, V184 is cleared by software

RST real-time key value is stored in V182 unit, key value is stored in V185 unit, V185 is cleared by software

V186: Input port i03 or i04 is cancelled by command. V186 = 0 is not enabled (default), V186 = 1 is enabled.

V187: Limit and servo alarm master switch Not enabled when V187 = 1 (default), enabled when V187 = 0

V188: Soft limit stop master switch Disabled when V188 = 1 (default), enabled when V188 = 0

V189: Input signal capture master switch Not enabled when V189 = 1 (default), enabled when V189 = 0

V143: Running pulse width (value range 0 ~ 400, automatically modified)

V142: Pulse width threshold (value range 4 ~ 400, artificial modification)

V141: G41, G06 DGREE smooth value (stop speed, artificial modification)

V140: Speed timing value (automatic change)

Port corresponding register value

(G06 SCAN = I during scanning, V144 ~ V159, V192 ~ V207: light on value is 0, light off value is 1)

i00: p0 v144

i01: p1 v145

i02: p2 v146

i03: p3 v147

i04: p4 v148

i05: p5 v149

i06: p6 v150

i07: p7 v151

i08: P8 v152

i09: P9 v153

i10: P10 v154

i11: P11 v155

i12: P12 v156

i13: P13 v157

i14: P14 v158

i15: P15 v159

HM0: P16 v192  
HM1: P17 v193  
HM2: P18 v194  
HM3: P19 v195  
HM4: P20 v196  
HM5: P21 v197

LP0: P22 v198  
LP1: P23 v199  
LP2: P24 v200  
LP3: P25 v201  
LP4: P26 v202  
LP5: P27 v203

ALM0: P28 v204  
ALM1: P29 v205  
ALM2: P30 v206  
ALM3: P31 v207  
O00: P0 v160  
O01: P1 v161  
O02: P2 v162  
O03: P3 v163  
O04: P4 v164  
O05: P5 v165  
O06: P6 v166  
O07: P7 v167  
O08: P8 v168  
O09: P9 v169  
O10: P10 v170  
O11: P11 v171  
O12: P12 v172  
O13: P13 v173  
O14: P14 v174  
O15: P15 v175

(V256 ~ V271: value 1 is capture enable, V189 = 0 takes effect)

ENi00: p0 v256  
ENi01: p1 v257  
ENi02: p2 v258  
ENi03: p3 v259  
ENi04: p4 v260  
ENi05: p5 v261  
ENi06: p6 v262

ENi07: p7 v263  
ENi08: P8 v264  
ENi09: P9 v265  
ENi10: P10 v266  
ENi11: P11 v267  
ENi12: P12 v268  
ENi13: P13 v269  
ENi14: P14 v270  
ENi15: P15 v271

(V288 ~ V303: capture time value, unit is millisecond, need to be cleared by software)

FLAGi00: p0 v288  
FLAGi01: p1 v289  
FLAGi02: p2 v290  
FLAGi03: p3 v291  
FLAGi04: p4 v292  
FLAGi05: p5 v293  
FLAGi06: p6 v294  
FLAGi07: p7 v295  
FLAGi08: P8 v296  
FLAGi09: P9 v297  
FLAGi10: P10 v298  
FLAGi11: P11 v299  
FLAGi12: P12 v300  
FLAGi13: P13 v301  
FLAGi14: P14 v302  
FLAGi15: P15 v303

// =====

Visual example

G08 CCD2:

G08 MOV V20 = # 0

G08 CCD2A:

G06 T = 401 // RCCD

G08 IF V20 == # 0 AJMP CCD2A

G08 END

When the host computer receives T = 401,

The upper computer sends instructions such as:

G20 X = 300 Y = 200 Z = 270 A = 0 B = 150 C = 0 D = 0 MOV V20 = # 1

G41 X = 300 Y = 200 Z = 270 A = 0 B = 150 C = 0 D = 0 MOV V20 = # 1

// .....

Examples of input signals

1, initialization, enable enable ENi07: p7 v263

G08 CSH:

```
G08 MOV V189 = # 0
```

```
G08 MOV V263 = # 1
```

```
G08 END
```

2. Read the captured FLAGi07: p7 v295 value during the run

```
G08 INSCAN:
```

```
G06 T = 500
```

```
G08 IF V295 > # 400 ACALL ZHOOU14
```

```
G08 MOV V295 = # 0
```

```
G08 AJMP INSCAN
```

```
G08 END
```

3, capture the v295 value greater than 400 milliseconds, then call ZHOOU14

```
G08 ZHOOU14:
```

```
G06 O = P14.1
```

```
G06 T = 400
```

```
G06 O = P14.0
```

```
G06 T = 400
```

```
G06 O = P14.1
```

```
G06 T = 400
```

```
G06 O = P14.0
```

```
G08 END
```

```
// =====
```

C language for, while implementation on PFOP

[1] For example:

```
int V0;
```

```
int V1 = 100;
```

```
for (V0 = 2, V0 < V1, V0 = V0 + 3)
```

```
{...}
```

```
...
```

[1] Implementation on PFOP:

```
G08 MOV V0 = # 2
```

```
G08 MOV V1 = # 100
```

```
G08 AJMP FOR1
```

```
G08 LABEL1:
```

```
G08 ADD V0 = V0 + # 3
```

```
....
```

```
G08 FOR1:
```

```
G08 IF_ELSE V0 < V1? AJMP LABEL1: AJMP LABEL2
```

```
G08 LABEL2:
```

```
...
```

[2] For example:

```

int V0;
int V1 = 100;
for (V0 = 2, V0 < V1, V0 = V0 + 3)
{
    ....
    if (V0 > 50) {break;}
    ....
}
...

```

[2] Implementation on PFOP:

```

G08 MOV V0 = # 2
G08 MOV V1 = # 100
G08 AJMP FOR1
G08 LABEL1:
G08 ADD V0 = V0 + # 3
....
G08 IF V0 > 50 AJMP LABEL2
....
G08 FOR1:
G08 IF_ELSE V0 < V1? AJMP LABEL1: AJMP LABEL2
G08 LABEL2:
...

```

[3] For example:

```

int V0 = 2;
int V1 = 100;
while (V0 < V1)
{
    V0 = V0 + 1
    ....
}
...

```

[3] Implementation on PFOP:

```

G08 MOV V0 = # 2
G08 MOV V1 = # 100
G08 AJMP FOR1
G08 LABEL1:
G08 ADD V0 = V0 + # 1
....
G08 FOR1:
G08 IF_ELSE V0 < V1? AJMP LABEL1: AJMP LABEL2
G08 LABEL2:
...

```

[4] For example:

```
int V0 = 2;
int V1 = 100;
while (V0 < V1)
{
    V0 = V0 + 1
    ....
    if (V0 > 50) {break;}
    ....
}
...
```

[4] Implementation on PFOP:

```
G08 MOV V0 = # 2
G08 MOV V1 = # 100
G08 AJMP FOR1
G08 LABEL1:
G08 ADD V0 = V0 + # 1
....
G08 IF V0 > 50 AJMP LABEL2
....
G08 FOR1:
G08 IF_ELSE V0 < V1? AJMP LABEL1: AJMP LABEL2
G08 LABEL2:
...
```


```
// =====
Parameter file
FILE = INI // File path
Parameter.ini // File name
510 // File length (counted from the fourth line to the end)
//// DH_PARAMETER: // DH parameters (unit: mm; h-bit length, d is distance)
_h0 = 203; // can be a dummy value
_d1 = 80;
_h2 = 260;
_d3 = 80;
_h4 = 288;
_h5 = 64.5;
_d6 = 40; // can be a dummy value
//// MOTOR_DIR: // Motor direction
_dir1 = -1;
```

```

_dir2 = 1;
_dir3 = 1;
_dir4 = -1;
_dir5 = 1;
_dir6 = -1;
//// JOINT_PUL: // Organization breakdown
_j1pul = 320000; // The mechanism needs 320000 pulses per circle
_j2pul = 326400;
_j3pul = 326400;
_j4pul = 320000;
_j5pul = 320000;
_j6pul = 320000;
//// VELOCITY:
_ac = 100000.0; // Acceleration
_de = 100000.0; // Deceleration
_vpp = 100000.0; // Full speed
_vp = 10; // speed degree
//// MODE:
_pve = 8.887 // Not used
_getCodeMode = 0; // 0 means teach for joint output, 1 teach for right angle output
_runCodeMode = 1; // 1 is the printing code, 0 is not printing the code
_prmTPUL = 120; // Pulse maximum width adjustment threshold (4 ~ 400) (V142)
_prmVLIM = 2000; // G41 smoothing value (V141)
// REPOS // ===== power-on default angle =====
_rePosJ1 = 0;
_rePosJ2 = 0;
_rePosJ3 = -90;
_rePosJ4 = 0;
_rePosJ5 = -90;
_rePosJ6 = 0;
// IRQ // ===== Interrupt switch =====
_iIRQ = 1 // Inductor limit enable switch: _iIRQ = 1 enable off, _iIRQ = 0 enable on, default 1;
_sIRQ = 1 // Soft limit enable switch: _sIRQ = 1 enable off, _sIRQ = 0 enable on, default 1;
_flagSoftRst = 1 // Serial port restart controller enable: _flagSoftRst = 1 enable on, _flagSoftRst =
0 enable off, default 0;
_brkMotorEn = 0 // brake enable: _brkMotorEn = 1 enable on, _brkMotorEn = 0 enable off,
default 1;
// LIMIT // ===== software limit =====
_slp0 = 175 // Software positive limit angle of the 1st axis
_sln0 = -175 // Software negative limit angle of the 1st axis
_slp1 = 90 // The second axis limit angle
_sln1 = -90 // The second axis limit angle
_slp2 = 30 // 3rd axis limit angle
_sln2 = -180 // 3rd axis limit angle

```

\_slp3 = 175 // 4th axis limit angle  
 \_sln3 = -175 // 4th axis limit angle  
 \_slp4 = 120 // 5th axis limit angle  
 \_sln4 = -120 // 5th axis limit angle  
 \_slp5 = 359 // The 6th axis limit angle  
 \_sln5 = -359 // The 6th axis limit angle



===== Six-axis robot Cartesian coordinate system =====

P (x, y, z, a, b, c, d)

x: X-axis distance (P-point X-axis component);

y: Y-axis distance (P-point Y-axis component);

z: Z-axis distance (P-point Z-axis component);

a: attitude plane angle;

The angle is the angle between the vector mapped by the attitude vector PQ in the XOY plane and the OX axis;

Angle range: (-180, 180);

b: attitude line face angle;

The angle b is the angle between the attitude vector PQ and the OZ axis;

Angle range: (0, 180);

c: attitude rotation angle;

The angle c is the angle between the vector mapped by the tool vector in the XOY plane and the OX axis;

Angle range: (-360, 360);

d: angle state of each joint in the model;

D is an integer, and no value defaults to 0;

Provisions:

0: The end is mapped to the positive direction, the same direction as D1 of the DH parameter, the third axis angle (-) sign, and the fifth axis angle (-) sign;

1: The end map is in the positive direction, the same direction as D1 of the DH parameter, the third axis angle (-) sign, and the fifth axis angle (+) sign;

2: The end is mapped in the positive direction, the same direction as D1 of the DH parameter, the third axis angle (+) sign, and the fifth axis angle (-) sign;

3: The end map is in the positive direction, the same direction as D1 of the DH parameter, the third axis angle (+) sign, and the fifth axis angle (+) sign;

4: The end is mapped in the negative direction, inverse to D1 of the DH parameter, the third axis angle (-) sign, and the fifth axis angle (-) sign;

5: The end is mapped in the negative direction, inverse to D1 of the DH parameter, the third axis angle (-) sign, and the fifth axis angle (+) sign;

6: The end is mapped in the negative direction, inverse to D1 of the DH parameter, the third axis angle (+) sign, and the fifth axis angle (-) sign;

7: The end is mapped to the negative direction, inverse to D1 of the DH parameter, the third axis angle (+) sign, and the fifth axis angle (+) sign;

## Program Case

```
FILE=ST
```

```
AM.ST
```

```
1719 //Sequence number of the program
```

```
code:
```

```
G07 VP=20 //Speed set to 20%
```

```
G00 J1=0 J2=0 J3=-90 J4=0 J5=-90 J6=0 //Run to door position
```

```
G20 X=300 Y=131 Z=55 A=0 B=180 C=0 D=0 //Run to a location
```

```
G06 O=P0.1 //Turn on output 00
```

```
G20 X=300 Y=131 Z=20 A=0 B=180 C=0 D=0 //Run to a location
```

```
G06 O=P0.0 //Turn off output 00
```

```
G06 T=500 //Delay 500 ms
```

```
G00 J1=0 J2=0 J3=-90 J4=0 J5=-90 J6=0 //Back door position
```

```
G08 EXIT //Exit the loop, Program ends
```